

Source area of 2019\_10\_31 slide upslope (left) of damaged dwelling at 68 Cavalier Drive. Portion of slide mass with displaced vegetation visible in photo middle ground. 2019\_11\_01 NCGS photo.



Skimmer discharge pipe above slide area. Overland water flow below outlet infiltrates into the slope immediately above the slide area. 2019\_11\_01 NCGS photo.





Figure 1

2019\_11\_01 NCGS UAS Image



2019\_10\_31 slide area and damaged dwelling



Top Right and Bottom Right. Standing water in sediment basin upslope of dwellings. 2019\_11\_01 NCGS photos.

Figure 2