

Sedimentation/Construction Stormwater Inspection Report

North Carolina Department of Environmental Quality
Land Resources: 2090 US Highway 70, Swannanoa, NC 28778 (828) 296-4500

check dams and inlet protection as needed. Maintain all measures and make field adjustments as needed.

The NOV response received by this office on July 8, 2019 was found to be satisfactory. In accordance of the revised plan, the site is now in compliance. The NOV issued June 24, 2019 is lifted.

Reported by: Rick Brooks

Others present:

Date of inspection: July 10, 2019

Time arriving on site: 10:00 AM **Time leaving site:** 11:00 AM

cc: